Marksman Solo 11.1 Firmware/Software Release

To: FoxJet Distribution Network
From: Terry Smith
Date: 05/22/2017 Technical Bulletin TB20170522

Controller:	Marksman HHI Plus & HHI
Printers	Solo 45, Solo 90
New Solo Firmware Version:	sh_11-1-1704051732
New HHI & Plus Firmware Version:	o_11-1-1704051145
New PC Software Version:	pcs_11-1-1704051
New Manual Versions:	5780-649FX, Rev. B & 5780-329, Rev. M

FoxJet has released Solo 11.1 firmware for the Solo 45 and 90 Printers.

New languages: Korean user interface and Keyboard. Hebrew keyboard (no Hebrew interface).

Status Screen Ink level indicator, shows a percentage of ink remaining in the Ink Cartridge.

The HHI now has the "45si print cartridge" setting in the Print Head setup screen, like the HHI Plus.
(This gives the Customer the ability to use Solo 450NP Ink, with the HHI).



Compatibility

Solo 11.1 (sh_11-1…) is compatible with the older firmware versions used on the original HHI and the Duo. However, the new HHI Plus is not compatible with Solos using firmware Version 9.3 or below. See Compatibility section in TB20150916 Solo 10.2 Release for upgrade information.
(o_11-1... is compatible with the original HHI using V8.x and up. It is not compatible with V7.x and below.)

Availability

To obtain a copy of Solo sh_11-1 Firmware, o_11-1 for the HHI and HHI Plus, and pcs_11-1 Software for P.C., go to www.foxjet.com.
The Firmware/Software is under the "Updates/SoloSeries" menu.
The new Manual is under the "Products/Thermal Inkjet/Marksman HHI Plus/Manuals".